

Radiography TEST Report for Piping

Report No.	KSM-ASU-960	Reference Standard:	ASME B 31.3	RT Device SN:	212	Density:	2-4	Received Dose(μv)	Geiger	Dosimeter	Radiographer Name	Personal Code									
Report Date:	14/05/1405	RT Instruction No.	J-104-IN-33	KV:		Sensitivity:	1/2		---	0	هومان نادرى	1205									
Radiography Date:	07/05/1405	RT Technique:		Source Power:	39 ci	Film Type:	MX125-PB-10	20μsv	PC-534	0	مهدي تالاب	1159									
Request No.	SSA-RQ-533	SWSI ☒	DWSI ☐	DWDI ☐	Source Size:	2 mm	Total Film Length:	1.920CM	30μsv	PC-531	0	محمد امين تومى	1244								
Page:	1/1	IQI	10 - 16	Fe	EN	Exposure Time:	40min	Spilled Film:	---	---	---										
Number of locations:	4	Total request (inch diameter/film sheet):			200	Number of radiographic lesions:		4	Total radiographed (inch diameter/film sheet):			200(inch)	Start time:	0:00	End time:	2:20					
Row	Joint No.	Line No.	RT No.	Size (inch)	Thk (mm)	Film Size	Segment	Material	Welder Stamp		Welding Process	Joint Type	Req No.	Weld Defect		Accept	Regrader	Reheat	Reale	Cut-Out	Remark
1	21	GWN-701202	ASU-1990	56	12.7	40*13		CS	GWC-026	-37			SSA-RQ-5			☒	☐	☐	☐	☐	
2	22	GWN-701202	ASU-1991	44	12.7	40*11		CS	GWC-08	-37			SSA-RQ-5			☒	☐	☐	☐	☐	
3	25	GWN-701202	ASU-1987	56	12.7	40*13		CS	GWC-026	-37			SSA-RQ-5			☒	☐	☐	☐	☐	
4	26	GWN-701202	ASU-1992	44	12.7	40*11		SS	GWC-026	-37			SSA-RQ-5			☒	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*										☐	☐	☐	☐	☐	
						*															