

Radiography TEST Report for Pipeline

Report No.	KSM-SAT-108	Reference Standard:	API 1104	RT Device S/N:	1912	Density:	2-4	Received Dose(μsv)		Geiger		Dosimeter		Radiographer Name	Personnel Code						
Report Date:	14/05/1405	RT Instruction No.:	J-104-IN-28	RV:		Sensitivity:	I-2							محمد تاجری	1285						
Radiography Date:	08/05/1405	RT Technique:		Source Power:	14 ci	Film Type:	MK25-PM-10	30gusv							1159						
Request No.:	SAT-RQ-698	SWI: ☐	DWSI: ☒	DWDI: ☐	Exposure Rate:	2-2	Total Film Length:	0CM													
Page:	1/1	IQI	10-16	Fe	EN	Exposure Time:	80min	Spooled Film:													
Number of locations:	2	Total request (inch diameter/film sheet):			40	Number of radiographic lesions:			0	Total radiographed (inch diameter/film sheet):			(inch)	Start time:							
Row	Joint No.	Line No.	RT No.	Size (inch)	Thk (mm)	Film Size	Segment	Material	Welder Stamp		Welding Process	Joint Type	Req No.	Weld Defect	Accept	Regrate	Retouch	Recheck	End time:	0:30	Remark
									W1	W2											
						*							SAT-RQ-07		☐	☐	☐	☐			
						*							SAT-RQ-07		☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*									☐	☐	☐	☐			
						*	</														