

Radiography TEST Report for Pipeline

Report No.	KSM-SAT-105	Reference Standard:	API 1104	RT Device S/N:	212	Density:	2-4	Received Dose(µsv)		Geiger		Dosimeter		Radiographer Name	Personnel Code			
Report Date:	14/05/1405	RT Instruction No.	J-104-IN-28	R.V.		Sensitivity:	I-2					0		هومان ناکری	1205			
Radiography Date:	09/05/1405	RT Technique:		Source Power:	37 cl	Film Type:	MSJ-19-18	30µsv										
Request No.	SAT-RQ-098	SWS ☐ DWSI ☒ DWDII ☐		Source Size:	2-2	Total Film Length:	48BCM	50µsv						میدان خانی	1139			
Page:	1/1	IQI	10 - 16	Fe	EN	Exposure Time:	80min	Spooled Film:										
Number of locations:	2	Total request (inch diameter/film sheet):	48	Number of radiographic lesions:	2	Total radiographed (inch diameter/film sheet):	48(inch)	Start time:	21:00	End time:	0:30							
Row	Joint No.	Line No.	RT No.	Size (inch)	Thk (mm)	Film Size	Segment	Material	Welder Stamp	Welding Process	Joint Type	Req No.	Weld Defect	Accept	Repair	Retest	Re-eval	Remark
1	2415 C	24" METHANOL-UG	KSM-485	24	7.92	40*6		CS	W-02	-1		SAT-RQ-0		☒	☐	☐	☐	
2	2420 C	24" METHANOL-UG	KSM-490	24	7.92	40*6		CS	W-02	-1		SAT-RQ-0		☒	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*								☐	☐	☐	☐	
B						*		</										